



Salt Lake Office
 501 West 700 South
 Salt Lake, UT 84101
 PH: 801.366.4100
 PH: 800.433.4548
 FX: 801.531.8896

Denver Office
 4905 B Ironton St.
 Denver, CO 80239
 PH: 303.574.9448
 PH: 800.511.7734
 FX: 303.574.9389

Boise Office
 Boise, ID
 PH: 208.573.1038
 PH: 800.433.4548

Portland Office
 Portland, OR
 PH: 503.616.4677
 PH: 800.433.4548

Competitive Comparison

When deciding on a Motor Shop for your repairs, ask them the following questions:

	Competition	C.W.Silver
Do you have a “Core Loss Tester” to detect hidden damage to the stator iron (laminations)?	?	Yes
Do you have a “Temperature Controlled Burnout Oven” to prevent over temperature and damage to the stator iron? Do you provide a chart of temperature during burnout?	?	Yes
Do you use “1600 Volt Spike Resistant Wire” in all rewinds?	?	Yes
Do you perform “Inverter Duty Rewinds” on all random wound A-C motor rewinds?	?	Yes
If your shop has a “V.P.I. System” is it used on all rewinds?	?	Yes
Do you have an “Automatic Coil Winding Machine” which lays strands parallel, thus eliminating crossovers and high turn-to-turn potential?	?	Yes
Do you have a “Dynamometer” for load testing?	?	Yes
Do you have “U.L. Certification” for rewinding and repairs on explosion proof motors?	?	Yes
Do you have “Dynamic Balancing Equipment” to insure minimum vibration and a longer bearing life? Do you provide a vibration report on rotor as tested?	?	Yes

Offering Electrical Asset Management since 1917

